

ND = Non Detect - Lead level is below the set detection limits

Water Testing Results - Elmira High School Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Kitchen Sink	#1	8/28/2018	ND
Cafeteria Drinking Fountain	#2	8/28/2018	MD
Room 30 Sink	#3	8/28/2018	2.19ppb
Shop Hall Drinking Fountain	#4	8/28/2018	ND
Room 18 Sink	#5	8/28/2018	ND
Gym Hall Drinking Fountain	#6	8/28/2018	ND
Health Room Sink	#7	8/28/2018	ND
Room 16 Sink	#8	8/28/2018	5.34ppb
Senior Hall Drinking Fountain	#9	8/28/2018	ND
Aux Gym Drinking Fountain	#10	8/28/2018	ND

ND = Non Detect - Lead level is below the set detection limits

Water Testing Results - District Office Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
No taps yet tested			

ND = Non Detect - Lead level is below the set detection limits

Water Testing Results - District Maintenance Bldg. Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
No taps yet tested			

ND = Non Detect - Lead level is below the set detection limits

**Water Testing Results - Transportation Building
Action Level is 15 parts per billion (ppb)**

Fixture Location/Description	Fixture ID #	Test Date	Test Result
No taps yet tested			

ND = Non Detect - Lead level is below the set detection limits